



Service Info



Design change

Deflection pulley 532 0475 10

Manufacturer: BMW

Models: 1', X1, 3', X3, Z4, 5'

Engines: N40, N43, N45, N46, M43

Part no.: 532 0475 10

For current listing refer to catalogue media

As part of our continuous efforts to improve our products, modifications have been made to the tensioning pulley with part number 532 0475 10.

This Service Information sheet shows the visual features of the previous version (Figure 1) and the new version (Figure 2).

During the transition period, we may have mixed stocks of both types.

Both comply with the technical specifications and can be used without restrictions.



Figure 1: Previous design



Figure 2: New design

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264*

Fax: +44 (0) 1432 375 760

hfd-info@schaeffler.com

www.schaeffler-aftermarket.co.uk

* Calls from within the UK 08457 001100



SCHAEFFLER

REP>XPERT